

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15310 Main Street: PIERSON\_DR Cross Street: WOODHILL\_LN Location: E

ADA ID: 4651799E02D6 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

WOODHILL LN StopSign PIERSON DR None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance         Description           N/A         Ramp Length (in)           31.0         Yes           BlendTrans Slope (%)	<u>Data</u> 0.3
	0.3
No Ramp Width (in) 40.0 No BlendTrans XSlope (%)	6.8
N/A Flare Type LT N/A N/A Flare Type RT	N/A
N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%)	N/A
N/A Flare Traversable LT? N/A N/A Flare Traversable RT?	N/A
N/A Landing Length (in) N/A N/A DWS Provided?	N/A
N/A Landing Width (in) N/A N/A DWS Contrast?	N/A
N/A Landing Slope (%) N/A N/A DWS Length (in)	N/A
N/A Landing X Slope (%) N/A N/A DWS Full Width?	N/A
N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in)	N/A
N/A Shared Landing? N/A	
N/A Gutter Ponding? N/A N/A Gutter Slope (%)	N/A
N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%)	N/A
N/A Painted X Walk1? No N/A Painted X Walk2?	No
X Walk 1 Direction To NW X Walk 2 Direction	To SW
X Walk 1 Width (in) N/A X Walk 2 Width (in)	N/A
X Walk 1 Slope (%) 1.5 X Walk 2 Slope (%)	7.4
X Walk 1 X Slope (%) 7.0 X Walk 2 X Slope (%)	1.2
N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2?	N/A
Road Slope (%) 5.3 Clear Space?	N/A
Road X Slope (%) 5.6 N/A Clear Space to XWalk (i	n) <b>N/A</b>
N/A Any Obstructions? N/A N/A Storm Grate/Utility Haza	rd? <b>N/A</b>
Obstruction Type Storm Grate/Utility Type	
N/A	N/A
Yes Surface Condition? (G/F	) Good
No Curb Slope (%)	9.5
and clope (%)	0.0





