

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.2

4.7

N/A

No

To N

N/A

3.4

0.7

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 47273Main Street:LAMPLIGHTER_CLOSE_DRCross Street:LIDDINGTON_RDLocation:SWADA ID: 488B6547176DRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:10

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

3200.00

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

48.0

45.0

N/A

No

To E

N/A

2.5

2.3

N/A

4.6

2.2

N/A

N/A



Street 1 Name

Stop Condition-Street 2

Street 2 Name

Stop Condition-Street 1

StopSign

Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.
Surveyor Notes: N/A
PROW/ADA: Not Found, R304.5.1, R304.5.3





Total Cost:

