

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14311	Main Street: BERKELEY_AV			Cross Street: CARLTON_AV				Location:	NE
ADA ID: 49299B8382AA	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Arrest	Possible Solutions:		Compliance Description			Data Compliance Description		
V Start and T	10 73	Remove & Replace Entire Ram).	N/A	Ramp Length (in)	54.0	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0
A LAND AND AND AND AND AND AND AND AND AND	244 2			Yes	Ramp Slope (%)	5.6	N/A	Grade Break XSlope (%)	0.0
1 / Stored States	a la state			No	Ramp XSlope (%)	3.1			
	any the			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	mar yes			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
L S L &	NAR.	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
J T		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
Contraction of the second seco	E - Y -			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
the second second	Pro the			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
E.E.	A			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	1 de la	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
See Anne Anne A	A KAN	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	and the			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
A LE LANGE	Ales			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
as Aller a log and a	6422			N/A	Painted X Walk1?	No		Road Slope (%)	8.5
Street 1 Name	CARLTON AV				X Walk 1 Direction	To W		Road X Slope (%)	0.5
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	8.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.5	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	11.9

