

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.0

1.8

N/A

Good

Intersection ID: 50370 Main Street: GENEVIEVE CT **Cross Street: COUNTRY LN** Location: SE

Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 4A037F8DE4B1 Ramp Type: Perp **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

47.0

45.5

N/A

No

To W

N/A

0.2

2.3

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



GENEVIEVE CT Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

<u> </u>	1 COCIDIO COIGNON			i ioia iiio
	Possible Solutions:	Compli	ance	Description
200	Remove & Replace Entire Ramp.	N/A	Ramp	Length (in)
1	•	No	Ramp	Width (in)
		N/A	Flare	Type LT
1		N/A	Flare	Slope LT (%)
200		N/A	Flare	Traversable L1
1		N/A	Landir	ng Length (in)
	Surveyor Notes:	N/A	Landir	ng Width (in)
10	N/A	N/A	Landir	ng Slope (%)
行行		N/A	Landir	ng X Slope (%
		N/A	Landir	ng Curb? (Y/N
200		N/A	Share	d Landing?
	PROW/ADA:	N/A	Gutter	Ponding?
Š	Not Found, R304.5.1	N/A	Gutter	Lip Ht (in)
4		N/A	Painte	d X Walk1?
			X Wall	1 Direction
į,		N/A	X Wall	k 1 Width (in)
			X Wall	k 1 Slope (%)
			X Wall	k 1 X Slope (%
		N/A	Ramp	inside XWalk
			Road	Slope (%)





Total Cost:



N/A

1850.00