cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| · · · · | | | | | | | | | | |
|---|--------------|--|--------------|---|-------------------|-------|-----------------------------|-----------------------------|-------|--|
| Intersection ID: 31666 | Main Str | Cross Street: STARSHINE_DR | | | | | Location: | SE | | |
| ADA ID: 4A38B3D8A5E9 | Ramp Ty | /pe: PerpDiag | Initial Pass | /Fail: Fail | Severity Score: | 33.75 | | | | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| | | Possible Solutions: | Co | Compliance Description | | | Data Compliance Description | | | |
| | | Remove & Replace Curb Ramp W | /ith N/A | Ramp Lengt | h (in) | 8.0 | No | Ramp Slope (%) | 11.2 | |
| | | Two New Directional Ramps or | No | Ramp Width | (in) 4 | 0.0 | No | Ramp XSlope (%) | 6.9 | |
| | | Equivalent. | N/A | Flare Type L | T | N/A | N/A | Flare Type RT | N/A | |
| | | | N/A | Flare Slope | LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | | N/A | Flare Traver | sable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| the Barks | | | N/A | Landing Len | igth (in) | N/A | N/A | DWS Provided? | N/A | |
| | | Surveyor Notes: | N/A | Landing Wic | lth (in) | N/A | N/A | DWS Contrast? | N/A | |
| | | N/A | N/A | Landing Slo | ре (%) | N/A | N/A | DWS Length (in) | N/A | |
| | | | N/A | Landing X S | lope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | | | N/A | Landing Cur | b? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| | | | N/A | Shared Land | ding? | N/A | | | | |
| | | PROW/ADA: | N/A | Gutter Pond | ling? | N/A | N/A | Gutter Slope (%) | N/A | |
| MEN DO | | Not Found, R304.5.1, R304.2.2, R304.5.3 | N/A | Gutter Lip H | t (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| ST ST ST ST | 100 | | N/A | Painted X W | /alk1? | No | N/A | Painted X Walk2? | No | |
| A De Ch | 10 mars | | | X Walk 1 Dir | rection To | w | | X Walk 2 Direction | To SW | |
| The second second | | | N/A | X Walk 1 Wi | dth (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name | EAVES LN | | | X Walk 1 Slo | ope (%) | 7.2 | | X Walk 2 Slope (%) | 2.3 | |
| Stop Condition-Street 2 | None | | | X Walk 1 X S | Slope (%) | 1.4 | | X Walk 2 X Slope (%) | 6.1 | |
| Street 2 Name | STARSHINE DR | | N/A | Ramp inside | e XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | StopSign | | | Road Slope | (%) | 5.1 | N/A | Clear Space? | N/A | |
| | | | | Road X Slop | be (%) | 4.4 | N/A | Clear Space to XWalk (in) | N/A | |
| | | | N/A | Any Obstruc | tions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | Total Cost: \$ 32 | 200.00 | Obstruction | Туре | | | Storm Grate/Utility Type | | |
| | | | | | | N/A | | | N/A | |
| | | | | | | - I· | Yes | Surface Condition? (G/P) | Good | |





