cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4676	eet: FRIENDSHIP_VILLAGE	RIENDSHIP_VILLAGE_PL Cross Street: MISSIONARY_AV						Location:	SW	
ADA ID: 4A9908A958	ADA ID: 4A9908A95893 Ramp Type: PerpDiag			Initial	Pass/Fa	ail: Fail Overall	o Severity Score:	31.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
A Start Contract		Possible Solutions:			Compliance Description		Data Compliance Description		liance Description	Data
THE REPORT		Remove & Replace Curb Ra Two New Directional Ramp Equivalent.	amp	With	N/A	Ramp Length (in)	73.0	No	Ramp Slope (%)	10.4
THE PERSON			•		No	Ramp Width (in)	35.0	Yes	Ramp XSlope (%)	4.6
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
L. A. B. B.					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
MILAC					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
ENENDSILL'ene		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	6. \ ^{6.}	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A WORK WI	- Jack Kan				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
And A LANK THE					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
a state of the second second	and the second	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
All the state	States i fere	Not Found, R304.5.1, R304	1.2.2		N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A
	前旗 编奏命				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
and the set of	e the the the fail					X Walk 1 Direction	To E		X Walk 2 Direction	To N
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	MISSIONARY AV					X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	3.8
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	4.4
Street 2 Name	FRIENDSHIP VILLAGE PL				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None					Road Slope (%)	4.8	N/A	Clear Space?	N/A
						Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A
1								•		

Yes Surface Condition? (G/P)

Good





