


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A	Main Street: LABEAU_AV	Cross Street: MORABLIN_DR	Location: W
ADA ID: 4AD8BE857445	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 33.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	Compliance
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		No	Ramp Length (in)	123.0	No
			No	Ramp Width (in)	44.0	No
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3			N/A	Flare Type RT	N/A	N/A
			N/A	Flare Slope RT (%)	N/A	N/A
			N/A	Flare Traversable RT?	N/A	N/A
			N/A	DWS Provided?	N/A	N/A
			N/A	DWS Contrast?	N/A	N/A
			N/A	DWS Length (in)	N/A	N/A
			N/A	DWS Full Width?	N/A	N/A
			N/A	DWS Offset (in)	N/A	N/A
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
Total Cost: \$ 3200.00			No	Painted X Walk1?	No	N/A
			To SE	X Walk 1 Direction	To SE	To N
			N/A	X Walk 1 Width (in)	N/A	N/A
			10.7	X Walk 1 Slope (%)	10.7	0.4
			0.3	X Walk 1 X Slope (%)	0.3	8.7
			N/A	Ramp inside XWalk1?	N/A	N/A
			7.7	Road Slope (%)	7.7	N/A
			6.6	Road X Slope (%)	6.6	N/A
			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		
			N/A		N/A	N/A
			Yes	Surface Condition? (G/P)	Good	Good

