

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 13227 | Main Street: SUNNYSIDE_AV | | | Cross | Street: | LAMAR_AV | Location: | SE | | |
|--|---------------------------|-------------------------|-----|---|--|-----------------------|-----------|--------------------|-----------------------------|-------|
| ADA ID: 4BA5B9A298EF | | | | Initial | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 13.75 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| Possible Solutions: | | | | Comp | liance Description | liance Description | Data | | | |
| | | Remove & Replace Entire | Ram | D. | N/A | Ramp Length (in) | 44.0 | N/A | Grade Break? | N/A |
| manufanda IS Son | | 1 | | P - | Yes | Ramp Width (in) | 73.0 | N/A | Grade Break Slope (%) | 0.0 |
| | | | | | No | Ramp Slope (%) | 9.0 | N/A | Grade Break XSlope (%) | 0.0 |
| A A A A A A A A A A A A A A A A A A A | | | | | No | Ramp XSlope (%) | 3.5 | | | |
| | O. L. Stall | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| the second secon | - A CON | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | 0.0 |
| SUNNYSI | DELAW | Surveyor Notes: | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| S Charles Constraint | EN/ | N/A | | | N/A | Landing Length (in) | 0.0 | N/A | DWS Provided? | N/A |
| | | | | | N/A | Landing Width (in) | 0.0 | N/A | DWS Contrast? | N/A |
| | States - | | | | N/A | Landing Slope (%) | 0.0 | N/A | DWS Length (in) | N/A |
| | | | | | N/A | Landing X Slope (%) | 0.0 | N/A | DWS Full Width? | N/A |
| | | PROW/ADA: | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset LT (in) | N/A |
| | Il and it | R304.2.2, R304.5.3 | | | N/A | Shared Landing? | N/A | N/A | DWS Offset RT (in) | N/A |
| | A LE I | , | | | N/A | Gutter Ponding? | 0.0 | N/A | Gutter Slope (%) | N/A |
| AL AND A CALL | | | | N/A | Gutter Lip Ht (in) | 0.0 | N/A | Gutter X Slope (%) | N/A | |
| | | | | | N/A | Painted X Walk1? | No | | Road Slope (%) | 6.6 |
| Street 1 Name | LAMAR AV | | | | | X Walk 1 Direction | To W | | Road X Slope (%) | 2.6 |
| Stop Condition-Street 1 | None | | | | | X Walk 1 Width (in) | N/A | | Clear Space? | N/A |
| Street 2 Name | N/A | | | | | X Walk 1 Slope (%) | 6.6 | N/A | Clear Space to XWalk (in) | N/A |
| Stop Condition-Street 2 | N/A | | | | | X Walk 1 X Slope (%) | 2.6 | N/A | Storm Grate/Utility Hazard? | N/A |
| | | | | | N/A | Ramp inside XWalk1? | N/A | | Storm Grate/Utility Type | |
| | | | | | N/A | Any Obstructions? | N/A | | | N/A |
| | | Total Cost: | \$ | 1600.00 | | Obstruction Type | | Yes | Surface Condition? (G/P) | Good |
| | | | | | | | N/A | N/A | Curb Slope (%) | 10.4 |

