

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 17310	310 Main Street: QUEENS_RD_WEST			Street:	SELWYN_AV	Location:	NE				
ADA ID: 4BB17D6E6282	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				26.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	Rea In Pro	Possible Solutions:		Compliance Description			Data Compliance Description				
		Remove & Replace Entire Ram	<b>)</b> .	N/A	Ramp Length (in)	89.0	N/A	Grade Break?	N/A		
	1 Stante			Yes	Ramp Width (in)	57.0	N/A	Grade Break Slope (%)	0.0		
	Martin L 14			No	Ramp Slope (%)	14.0	N/A	Grade Break XSlope (%)	0.0		
				No	Ramp XSlope (%)	4.0					
	WE I THE WAY I THE W			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
The shall be a first a	Red Star			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0		
	a state and the second	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
the second se	AND A CONTRACTOR	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A		
	A COMPANY OF THE PARTY OF THE P			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A		
QUEENS_RD_WEST				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
	WEST			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A		
	HALL BELLEVILLE	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A		
the UITE	AL COLOR	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A		
	ALL TON WALL	,		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A		
	Same Milli			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A		
				N/A	Painted X Walk1?	Yes		Road Slope (%)	3.8		
Street 1 Name	QUEENS RD WEST				X Walk 1 Direction	To S		Road X Slope (%)	3.5		
Stop Condition-Street 1	Signal				X Walk 1 Width (in)	112.0		Clear Space?	N/A		
Street 2 Name	N/A				X Walk 1 Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A		
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.5	N/A	Storm Grate/Utility Hazard?	N/A		
				N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type			
				N/A	Any Obstructions?	N/A			N/A		
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good		
						N/A	N/A	Curb Slope (%)	17.0		

