

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

12.5

2.1

N/A

Yes

To SE

112.0

0.1

3.1

Yes

N/A

N/A

N/A

N/A

Good

Intersection ID: 9565Main Street:N_TRYON_STCross Street:W_32ND_STLocation:NEADA ID: 4C54B04C324DRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:35

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

56.5

40.5

N/A

1.0

Yes

To SW

106.0

1.6

1.4

Yes

2.5

1.6

N/A

N/A



Street 1 Name W 32ND ST
Stop Condition-Street 2 Signal
Street 2 Name N TRYON ST
Stop Condition-Street 1 Signal

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.2.2

PROW/ADA:
R304.5.1, R304.2.2

Total Cost: \$ 3200.00

\$ 3200.00 Obstruction Type





