cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| · · · · · · · · · · · · · · · · · · · | | | | | | | | | |
|--|--------------------------|---|---------|---|-----------------------|-----------|--------------------|-----------------------------|------|
| Intersection ID: 12972 | Main Street: HAMORTON_PL | | | Street: | THOMAS_AV | Location: | SW | | |
| ADA ID: 4F49E7BC4358 | Ramp Type: PerpDiag | | | nitial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 12.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | Compliance Description Data Complia | | | liance Description | Data | |
| | | Remove & Replace Curb Ramp \ | Nith | N/A | Ramp Length (in) | 77.5 | Yes | Ramp Slope (%) | 5.5 |
| | | Two New Directional Ramps or Equivalent. | | Yes | Ramp Width (in) | 69.0 | No | Ramp XSlope (%) | 5.2 |
| | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| 5. | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| HAMORITON_PL & | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| and the second s | | | | N/A | Shared Landing? | N/A | | | |
| the second se | | PROW/ADA: | | N/A | Gutter Ponding? | Yes | N/A | Gutter Slope (%) | N/A |
| 1922 - 1921 | | Not Found, R304.5.3 | | N/A | Gutter Lip Ht (in) | 1.5 | N/A | Gutter X Slope (%) | N/A |
| A Contraction of the | | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | | | | | X Walk 1 Direction | To E | | X Walk 2 Direction | To N |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | THOMAS AV | - | | | X Walk 1 Slope (%) | 4.4 | | X Walk 2 Slope (%) | 2.7 |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 1.8 | | X Walk 2 X Slope (%) | 1.9 |
| Street 2 Name | HAMORTON PL | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | StopSign | | | | Road Slope (%) | 1.0 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 3.1 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| | | | | | | | Yes | Surface Condition? (G/P) | Good |

