


## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30252 Main Street: CENTENNIAL\_DR Cross Street: WYLAM\_DILLY\_CT Location: N

ADA ID: 50BC56DEFEF8 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

## Codes/Mitigation Info/Possible Solution





Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

CENTENNIAL DR StopSign WYLAM DILLY CT None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

CURB GAP 1.0

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Yes N/A Ramp Length (in) 48.0 BlendTrans Slope (%) 3.1 40.5 Yes No Ramp Width (in) BlendTrans XSlope (%) 1.4 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A Landing Length (in) N/A N/A **DWS Provided?** N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SW X Walk 2 Direction To SE N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) X Walk 2 Slope (%) 0.8 1.4 X Walk 1 X Slope (%) 2.9 X Walk 2 X Slope (%) 0.5 N/A N/A Ramp inside XWalk2? N/A N/A Ramp inside XWalk1? Road Slope (%) 2.0 Clear Space? N/A N/A Road X Slope (%) 3.6 Clear Space to XWalk (in) N/A

N/A

N/A

N/A

Yes

No

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

N/A

N/A

14.2

Good







N/A

Any Obstructions?

Obstruction Type