

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23840 Main Street: LONGLEAF\_DR Cross Street: TIMBERLINE\_RD Location: E

ADA ID: 5190C54CBBD5 Ramp Type: BlendTrans1 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 15

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 1

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent. Remove & Replace
Gutter.

Surveyor Notes:
N/A

PROW/ADA:

Not Found, R305, R304.5.4

Total Cost: \$ 3950.00

| Compliance Description Da |                       | Data   | Compliance Description |                             | Data   |
|---------------------------|-----------------------|--------|------------------------|-----------------------------|--------|
| N/A                       | Ramp Length (in)      | 58.0   | Yes                    | BlendTrans Slope (%)        | 2.4    |
| Yes                       | Ramp Width (in)       | 58.0   | Yes                    | BlendTrans XSlope (%)       | 0.8    |
| N/A                       | Flare Type LT         | Sloped | N/A                    | Flare Type RT               | Sloped |
| N/A                       | Flare Slope LT (%)    | 2.4    | N/A                    | Flare Slope RT (%)          | 0.3    |
| N/A                       | Flare Traversable LT? | No     | N/A                    | Flare Traversable RT?       | No     |
| Yes                       | Landing Length (in)   | 56.0   | No                     | DWS Provided?               | No     |
| Yes                       | Landing Width (in)    | 56.0   | N/A                    | DWS Contrast?               | No     |
| Yes                       | Landing Slope (%)     | 1.8    | N/A                    | DWS Length (in)             | N/A    |
| Yes                       | Landing X Slope (%)   | 2.0    | N/A                    | DWS Full Width?             | No     |
| N/A                       | Landing Curb? (Y/N)   | No     | N/A                    | DWS Offset (in)             | N/A    |
| N/A                       | Shared Landing?       | No     |                        |                             |        |
| Yes                       | Gutter Ponding?       | No     | No                     | Gutter Slope (%)            | 7.9    |
| Yes                       | Gutter Lip Ht (in)    | 0.0    | Yes                    | Gutter X Slope (%)          | 0.5    |
| N/A                       | Painted X Walk1?      | No     | N/A                    | Painted X Walk2?            | N/A    |
|                           | X Walk 1 Direction    | To SW  |                        | X Walk 2 Direction          | N/A    |
|                           | X Walk 1 Width (in)   | N/A    |                        | X Walk 2 Width (in)         | N/A    |
|                           | X Walk 1 Slope (%)    | 2.4    |                        | X Walk 2 Slope (%)          | N/A    |
|                           | X Walk 1 X Slope (%)  | 3.0    |                        | X Walk 2 X Slope (%)        | N/A    |
| N/A                       | Ramp inside XWalk1?   | N/A    | N/A                    | Ramp inside XWalk2?         | N/A    |
|                           | Road Slope (%)        | 3.0    |                        | Clear Space?                | Yes    |
|                           | Road X Slope (%)      | 2.4    | N/A                    | Clear Space to XWalk (in)   | N/A    |
| Yes                       | Any Obstructions?     | No     | Yes                    | Storm Grate/Utility Hazard? | No     |
|                           | Obstruction Type      |        |                        | Storm Grate/Utility Type    |        |
|                           |                       | N/A    |                        |                             | N/A    |
|                           |                       |        | Yes                    | Surface Condition? (G/P)    | Good   |
| No 6                      |                       |        | No                     | Curb Slope (%)              | 18.6   |





