cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8173 Main St	Main Street: CINDERELLA_RD		Cross Street: HIDDEN_VALLEY_RD				Location:	W
ADA ID: 51BDB0245C71 Ramp T	Ramp Type: BlendTrans1		Initial Pass/Fail: Fail Overall Compliance:			ce: No	Severity Score:	8.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description D			ata Compliance Description		
	Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	51.0	Yes	BlendTrans Slope (%)	3.3
	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	47.5	Yes	BlendTrans XSlope (%)	1.9
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Contraction of the second s			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	2.5	N/A	Gutter X Slope (%)	N/A
Not Found, Root.o.1			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name HIDDEN VALLEY RD				X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1 StopSign				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2 N/A				Road Slope (%)	0.5		Clear Space?	N/A
				Road X Slope (%)	4.8	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
	- ···· •				N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

22.9