

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

16.6

8.9

N/A

No

To E

N/A

3.5

3.3

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 45830 Main Street: EMMA LYNN CT Cross Street: CHRISTENBURY HILLS LN Location: NW **Severity Score: ADA ID: 53B4F1FC6A74** Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** 67.5

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Flare Traversable LT?

Flare Type LT

N/A

No

N/A

N/A

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

No

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

46.5

33.0

N/A

No

To S

N/A

0.0

6.2

N/A

7.4

2.4

N/A

N/A



**CHRISTENBURY HILLS LN** Street 1 Name Stop Condition-Street 2 None **EMMA LYNN CT** Street 2 Name Stop Condition-Street 1 StopSign Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, R304.5.3

N/A 3200.00

**Obstruction Type** 





Total Cost:

