

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 2396 | 6 Main Str | Main Street: CAROLINA_PAVILION_DR_N | | | | SOUTH_BV | Location: | SW | | |
|---|------------------------|-------------------------------------|--------------------|------------|---|--|-----------|------|-----------------------------|------|
| ADA ID: 53B5FBD4B | E0E Ramp Ty | Ramp Type: Perp | | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | 10 |
| Codes/Mitigation Info/Possible Solution | | | | | Field Measurements/Component Compliance | | | | | |
| | 1 8/10 | Possible Solutions: | | | Compliance Description D | | | Comp | Data | |
| 185 10 | 1 to a | Remove & Re | eplace Entire Ram | D . | N/A | Ramp Length (in) | 71.0 | Yes | Ramp Slope (%) | 5.3 |
| - <u>6</u> | T | | | | No | Ramp Width (in) | 47.0 | No | Ramp XSlope (%) | 2.4 |
| A WARMEN | L . | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | 1 man | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| 1 1 1 1 1 | | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | 75 0 | Surveyor Notes: | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| 2 James | E. | N/A | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| An AN | | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | | | N/A | Shared Landing? | N/A | | | |
| TI UN | | PROW/ADA: | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | | Not Found, F | R304.5.1, R304.5.3 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | , | , | | N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| | 1 Maker | | | | | X Walk 1 Direction | To NE | | X Walk 2 Direction | N/A |
| 1-1-1 | | | | | N/A | X Walk 1 Width (in) | 114.0 | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | CAROLINA PAVILION DR N | | | | | X Walk 1 Slope (%) | 0.6 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 2 | YieldSign | | | | | X Walk 1 X Slope (%) | 2.9 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | | | N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | N/A | | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| | | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: | \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | | N/A | | | N/A |
| | | | | | | | | Yes | Surface Condition? (G/P) | Good |

