

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29459 Main Street: N\_ALEXANDER\_ST Cross Street: GARDEN\_DISTRICT\_DR Location: E

ADA ID: 549E57F5CB8A Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

N ALEXANDER ST None GARDEN DISTRICT DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

C	ompliance	Description	Data	Comp	liance	Description	Data
N	/ <b>A</b> Ramı	p Length (in)	73.0	Yes	Blend	Trans Slope (%)	0.7
N	o Ramı	p Width (in)	47.5	No	Blend	dTrans XSlope (%)	5.8
N	/A Flare	Type LT	N/A	N/A	Flare	Type RT	N/A
N	/A Flare	Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N	/A Flare	Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N	/A Land	ing Length (in)	N/A	N/A	DWS	Provided?	N/A
N	/A Land	ing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N	/A Land	ing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N	/A Land	ing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N	/A Land	ing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N	/A Share	ed Landing?	N/A				
N	/A Gutte	er Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N	/A Gutte	er Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N	/A Paint	ed X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Wa	alk 1 Direction	To NW		X Wa	lk 2 Direction	To SW
	X Wa	ılk 1 Width (in)	N/A		X Wa	ılk 2 Width (in)	N/A
	X Wa	ılk 1 Slope (%)	4.1		X Wa	ılk 2 Slope (%)	0.3
	X Wa	ılk 1 X Slope (%)	3.0		X Wa	ılk 2 X Slope (%)	3.5
N	/ <b>A</b> Ram <sub>l</sub>	p inside XWalk1?	N/A	N/A	Ram	p inside XWalk2?	N/A
	Road	l Slope (%)	4.9		Clear	Space?	N/A
	Road	IX Slope (%)	0.1	N/A	Clear	Space to XWalk (in)	N/A
N	/A Any (	Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obst	ruction Type			Storn	n Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ice Condition? (G/P)	Good
				No	Curb	Slope (%)	9.5





