


Intersection ID: 29169	Main Street: CHIEFTAIN_DR	Cross Street: FIRESTREAK_DR	Location:	SW
ADA ID: 54F91FC4284B	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 8.75

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



### Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**NO LT SW**

PROW/ADA:

**Not Found, R304.5.1**

Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>	N/A	Ramp Length (in)	44.0	Yes	BlendTrans Slope (%)	3.9	
	No	Ramp Width (in)	47.5	Yes	BlendTrans XSlope (%)	0.5	
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	N/A	Shared Landing?	N/A				
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Surveyor Notes: <b>NO LT SW</b>		X Walk 1 Direction	To N		X Walk 2 Direction	N/A	
		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	1.1		X Walk 2 Slope (%)	N/A	
		X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A	
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
		Road Slope (%)	2.8		Clear Space?	N/A	
		Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A	
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Obstruction Type			Storm Grate/Utility Type		
			N/A			N/A	
				Yes	Surface Condition? (G/P)	Good	
				No	Curb Slope (%)	8.2	
Total Cost:	\$	3200.00					

**Total Cost: \$ 3200.00**

