

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

1.2

Intersection ID: N/A	Main Street: TWITTER_LN			Cross	Street:	ROCKY_RIVE	Location:	NE		
ADA ID: 575D2542EDB9	2EDB9 Ramp Type: Para			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	Possible Solutions:							bliance Description	Data	
	and a	Remove & Replace Entire	Ran	nn	N/A	Ramp Length LT (Ramp Length RT (in)	55.0
			Itan		Yes	Ramp Width LT (ir	()	Yes	Ramp Width RT (in)	60.0
					Yes	Ramp Slope LT (%	,	No	Ramp Slope RT (%)	9.1
					No	Ramp XSlope LT	(%) 2.4	Yes	Ramp XSlope RT (%)	1.2
				N/A	Landing Length (ir		N/A	DWS Provided?	N/A	
	4			N/A	Landing Width (in)	,	N/A	DWS Contrast?	N/A	
6 6 ⁶		Surveyor Notes:			N/A	Landing Slope (%) N/A	N/A	DWS Length (in)	N/A
m. 15	200	N/A			N/A	Landing X Slope (%) N/A	N/A	DWS Full Width?	N/A
All the second sec	E B				N/A	Landing Curb? (Y		N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	, N/A			
AL AL					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	PROW/ADA:			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
A. M. Bally	R304.5.3, R304.3.2			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
Market Contraction of the	Carlo and					X Walk 1 Directior	ז דס W		X Walk 2 Direction	N/A
and the set the second	and the				N/A	X Walk 1 Width (ir	ו) N/A	N/A	X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%	⁶) 3.0		X Walk 2 Slope (%)	N/A
Street 1 Name TV	WITTER LN	_				X Walk 1 X Slope	(%) 1.6		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	None				N/A	Ramp inside XWa		N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A					Road X Slope (%)) N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions	? N/A	N/A	Storm Grate/Utility Hazard?	N/A
						Obstruction Type			Storm Grate/Utility Type	
		Total Cost:	\$	1600.00			N/A			N/A
								Yes	Surface Condition? (G/P)	Good

