


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | | |
|------------------------|-------------------------------|-----------------------------|------------------------|----------------------|
| Intersection ID: 28415 | Main Street: CHASTAIN_WALK_DR | Cross Street: TREEBRANCH_DR | Location: | W |
| ADA ID: 5863D740AFE9 | Ramp Type: Perp | Initial Pass/Fail: Fail | Overall Compliance: No | Severity Score: 12.5 |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | | | | | | |
|--|--|----------------------|---|-----------------------|-------------------|--------------------|--|--------------------------|-----------------------|--|-------------|--|--|
|  | Possible Solutions: | | Compliance | | | Description | | | Data | | | | |
| | Remove & Replace Entire Ramp. | | N/A | Ramp Length (in) | | 48.0 | | No | Ramp Slope (%) | | 8.8 | | |
| | | | Yes | Ramp Width (in) | | 57.5 | | Yes | Ramp XSlope (%) | | 1.1 | | |
| | | | N/A | Flare Type LT | | N/A | | N/A | Flare Type RT | | N/A | | |
| | | | N/A | Flare Slope LT (%) | | N/A | | N/A | Flare Slope RT (%) | | N/A | | |
| | | | N/A | Flare Traversable LT? | | N/A | | N/A | Flare Traversable RT? | | N/A | | |
| | | | N/A | Landing Length (in) | | N/A | | N/A | DWS Provided? | | N/A | | |
| | | | N/A | Landing Width (in) | | N/A | | N/A | DWS Contrast? | | N/A | | |
| | | | N/A | Landing Slope (%) | | N/A | | N/A | DWS Length (in) | | N/A | | |
| | | | N/A | Landing X Slope (%) | | N/A | | N/A | DWS Full Width? | | N/A | | |
| Surveyor Notes: | | | | | N/A | | | | | | | | |
| PROW/ADA: | | | | | R304.2.2 | | | | | | | | |
| Street 1 Name | | TREEBRANCH DR | | | | | | | | | | | |
| Stop Condition-Street 2 | | StopSign | | | | | | | | | | | |
| Street 2 Name | | N/A | | | | | | | | | | | |
| Stop Condition-Street 1 | | N/A | | | | | | | | | | | |
| Total Cost: | | \$ 1850.00 | | | | | | | | | | | |
| | | | | | Compliance | | | Description | | | Data | | |
| | | | | | N/A | | | Ramp Length (in) | | | 48.0 | | |
| | | | | | Yes | | | Ramp Width (in) | | | 57.5 | | |
| | | | | | N/A | | | Flare Type LT | | | N/A | | |
| | | | | | N/A | | | Flare Slope LT (%) | | | N/A | | |
| | | | | | N/A | | | Flare Traversable LT? | | | N/A | | |
| | | | | | N/A | | | Landing Length (in) | | | N/A | | |
| | | | | | N/A | | | Landing Width (in) | | | N/A | | |
| | | | | | N/A | | | Landing Slope (%) | | | N/A | | |
| | | | | | N/A | | | Landing X Slope (%) | | | N/A | | |
| | | | | | N/A | | | Landing Curb? (Y/N) | | | N/A | | |
| | | | | | N/A | | | Shared Landing? | | | N/A | | |
| | | | | | N/A | | | Gutter Ponding? | | | N/A | | |
| | | | | | N/A | | | Gutter Lip Ht (in) | | | N/A | | |
| | | | | | N/A | | | Painted X Walk1? | | | No | | |
| | | | | | | | | X Walk 1 Direction | | | To N | | |
| | | | | | N/A | | | X Walk 1 Width (in) | | | N/A | | |
| | | | | | | | | X Walk 1 Slope (%) | | | 2.5 | | |
| | | | | | | | | X Walk 1 X Slope (%) | | | 0.8 | | |
| | | | | | N/A | | | Ramp inside XWalk1? | | | N/A | | |
| | | | | | | | | Road Slope (%) | | | N/A | | |
| | | | | | | | | Road X Slope (%) | | | N/A | | |
| | | | | | N/A | | | Any Obstructions? | | | N/A | | |
| | | | | | | | | Obstruction Type | | | | | |
| | | | | | | | | | | | N/A | | |
| | | | | | | | | | | | Yes | | |
| | | | | | | | | Surface Condition? (G/P) | | | Good | | |

