cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| | | | | | | | | CIAL |
|--|---|------------------------|---|-----------------------|-----------------------------|-------------------|-----------------------------|------|
| | Main Street: S_MINT_ST | | eet: | W_WORTHINGTON_A | Location: | SW | | |
| ADA ID: 58F38938F545 Ram | 5 Ramp Type: PerpDiag | | Initial Pass/Fail: Fail Overall Compliance: N | | | o Severity Score: | 12.5 | |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | |
| K PROTATION AND A | Possible Solutions: | Compliance Description | | | Data Compliance Description | | | Data |
| | Remove & Replace Curb Ramp W | /ith N | / A | Ramp Length (in) | 87.0 | Yes | Ramp Slope (%) | 5.5 |
| | Two New Directional Ramps or Equivalent. | Y | es | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 5.1 |
| | | N | / A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | all | Ν | / A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | Ν | / A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | Ν | / A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | Surveyor Notes: | Ν | / A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | N/A | Ν | / A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | N | / A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | | Ν | / A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | N | / A | Shared Landing? | N/A | | | |
| Dim 6 | PROW/ADA: | N | / A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| AND | Not Found, R304.5.3 | N | / A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | All | N | / A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| and the second sec | | | | X Walk 1 Direction | To E | | X Walk 2 Direction | To N |
| | and a | N | / A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name S MINT | ST | | | X Walk 1 Slope (%) | 2.9 | | X Walk 2 Slope (%) | 1.6 |
| Stop Condition-Street 2 No | ne | | | X Walk 1 X Slope (%) | 0.1 | | X Walk 2 X Slope (%) | 7.0 |
| Street 2 Name W WORTHINGTON AV | | N | / A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 StopS | ign | | | Road Slope (%) | 5.1 | N/A | Clear Space? | N/A |
| | | | | Road X Slope (%) | 2.0 | N/A | Clear Space to XWalk (in) | N/A |
| | | N | / A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Total Cost: \$ 32 | 200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | N/A | | | N/A |

Yes Surface Condition? (G/P)

Good

