

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 51751Main Street: GOLF_LINKS_DRCross Street: GOLF_LINKS_DR_NLocation:NEADA ID: 591FD18D9AC2Ramp Type: PerpDiagInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

GOLF LINKS DR N StopSign GOLF LINKS DR None

| Possible Solutions: |
|--|
| Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. |
| Surveyor Notes: |
| N/A |
| PROW/ADA: |
| Not Found, R304.5.1, R304.5.3 |
| |
| |
| |

Total Cost: \$ 3200.00

| Field Measurements/Component Compliance | | | | | | | | |
|---|--------|-----------------------|------|--------|--------|-----------------------|------|--|
| | Compli | ance Description | Data | Compli | ance | Description | Data | |
| | N/A | Ramp Length (in) | 47.0 | Yes | Ramp | Slope (%) | 7.9 | |
| | No | Ramp Width (in) | 40.0 | No | Ramp | XSlope (%) | 5.8 | |
| | N/A | Flare Type LT | N/A | N/A | Flare | Type RT | N/A | |
| | N/A | Flare Slope LT (%) | N/A | N/A | Flare | Slope RT (%) | N/A | |
| | N/A | Flare Traversable LT? | N/A | N/A | Flare | Traversable RT? | N/A | |
| | N/A | Landing Length (in) | N/A | N/A | DWS | Provided? | N/A | |
| | N/A | Landing Width (in) | N/A | N/A | DWS | Contrast? | N/A | |
| | N/A | Landing Slope (%) | N/A | N/A | DWS | Length (in) | N/A | |
| | N/A | Landing X Slope (%) | N/A | N/A | DWS | Full Width? | N/A | |
| | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS | Offset (in) | N/A | |
| | N/A | Shared Landing? | N/A | | | | | |
| | N/A | Gutter Ponding? | N/A | N/A | Gutter | r Slope (%) | N/A | |
| | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter | r X Slope (%) | N/A | |
| | N/A | Painted X Walk1? | No | N/A | Painte | ed X Walk2? | No | |
| | | X Walk 1 Direction | To W | | X Wal | k 2 Direction | To S | |
| | N/A | X Walk 1 Width (in) | N/A | N/A | X Wal | k 2 Width (in) | N/A | |
| | | X Walk 1 Slope (%) | 5.9 | | X Wal | k 2 Slope (%) | 0.3 | |
| | | X Walk 1 X Slope (%) | 2.8 | | X Wal | k 2 X Slope (%) | 3.7 | |
| | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp | inside XWalk2? | N/A | |
| | | Road Slope (%) | 3.0 | N/A | Clear | Space? | N/A | |
| | | Road X Slope (%) | 1.7 | N/A | Clear | Space to XWalk (in) | N/A | |
| | N/A | Any Obstructions? | N/A | N/A | Storm | Grate/Utility Hazard? | N/A | |
| | | Obstruction Type | | | Storm | Grate/Utility Type | | |
| | | | N/A | | | | N/A | |
| | | | | Yes | Surfac | ce Condition? (G/P) | Good | |
| -04 | | | | | | | | |





