

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

4.3

0.4

N/A

N/A

Good

17.6

Intersection ID: 45175 Main Street: LINDEN_TREE_LN Cross Street: TORRELLE_DR Location: E

ADA ID: 59C7CA8BAFC7 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Type LT

N/A

No

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

45.0 Yes

N/A N/A

N/A N/A

Yes

Compliance Description

Flare Type RT

Flare Slope RT (%)

BlendTrans Slope (%)

BlendTrans XSlope (%)

Surface Condition? (G/P)

Curb Slope (%)

Data

47.0



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

TORRELLE DR StopSign LINDEN TREE LN None Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

N/A

Surveyor Notes:

Possible Solutions:

PROW/ADA:

Total Cost:

Not Found, R304.5.1







3200.00

	' ',			. ,	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 Direction	To W
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	0.5
	X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	1.7
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.7		Clear Space?	N/A
	Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A

Yes

No