

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3584Main Street:DIXIE_ANN_DRCross Street:CHOWNING_TAVERN_LNLocation:SWADA ID: 59E75C1568D7Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

CHOWING TAVERN LN
None
DIXIE ANN DR
StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 3200.00

Compliance Description		Data	Compliance		Description	Data
N/A	Ramp Length (in)	61.0	Yes	Ram	Slope (%)	5.0
No	Ramp Width (in)	41.0	Yes	Ramp XSlope (%)		1.2
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	То Е		X Wa	lk 2 Direction	To N
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.7		X Wa	lk 2 Slope (%)	1.9
	X Walk 1 X Slope (%)	2.9		X Wa	lk 2 X Slope (%)	0.0
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	1.7	N/A	Clear	Space?	N/A
	Road X Slope (%)	2.7	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storn	n Grate/Utility Type	
		N/A				N/A

Surface Condition? (G/P)

Good





