

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23944	Main Street: BOSHAM_LN			treet:	PRESCOTT_POND_L	Location:	w		
ADA ID: 5B00C433803F	03F Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:					liance Description	Data	
and the second s	2	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	48.0		Ramp Slope (%)	7.7
	1			No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	1.5
	a second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Eggs				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A AND			N/A	Landing Length (in)		N/A	DWS Provided?	N/A
e de la companya de	1 - 1 - 1	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	5.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
S & &	116			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	S AN			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	AN AN	R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	- Country			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
- A - 9 / BL	VI VI				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BOSHAM LN	-			X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

