

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

8.0

1.6

N/A

No

To N

N/A

2.3

2.9

N/A

N/A

N/A

N/A

N/A

Poor

Intersection ID: 46470 Main Street: CRANDON DR Cross Street: PEACH BUD LN Location: SW **Overall Compliance: No Severity Score:** 15 ADA ID: 5B1015490060 Ramp Type: PerpDiag Initial Pass/Fail: Fail

**Codes/Mitigation Info/Possible Solution** 

**CRANDON DR** 

StopSign

None

Field Measurements/Component Compliance

Yes

Yes

N/A

No

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

48.0

48.0

N/A

1.5

No

To E

N/A

1.3

1.7

N/A

3.0

4.7

N/A

N/A



Street 1 Name Stop Condition-Street 2 **PEACH BUD LN** Street 2 Name Stop Condition-Street 1

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R302.7

Total Cost: 3200.00

N/A Ramp Length (in) Yes Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A Any Obstructions?

Compliance Description

**Obstruction Type** 





