

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 4249	Main Str	eet: N_TRYON_ST	Cross Street: PAVILION_BV					Location:	SE
ADA ID: 5B35FA675BBE	Ramp Type: Perp			ss/Fa	nil: Fail Overall (Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
10 11 1 10		Possible Solutions:						Data	
La da		Remove & Replace Entire Ramp.	N	N/A	Ramp Length (in)	78.0	Yes	Ramp Slope (%)	5.6
A ST			١	res	Ramp Width (in)	49.0	No	Ramp XSlope (%)	3.8
TI TESTON			Ν	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
102 04			Ν	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
- Koreka			Ν	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
LAN A		Surveyor Notes:	N	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A A A A A		N/A	N	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	in the state		Ν	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
5			Ν	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			Ν	N/A	Shared Landing?	N/A			
		PROW/ADA:	Ν	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
the parts		Not Found, R304.5.3	Ν	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A Start Start		,	Ν	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
			N	N/A	X Walk 1 Width (in)	100.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PAVILION BV				X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			١	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

