

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9858Main Street:MERCURY\_STCross Street:N\_DAVIDSON\_STLocation:SWADA ID: 5B51ABE4A467Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:21.25

Codes/Mitigation Info/Possible Solution



AND DESCRIPTION OF THE PARTY OF	COLUMN TO SERVICE THE PARTY OF
Street 1 Name	N DAVIDSON ST
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	9
Remove & Replace Entire Ramp.	
•	N
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.1, R304.2.2	N
, , ,	N
	N

	4.70	



Total Cost:



1850.00

Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance	Description	Data	
N/A	Ramp Length (in)	57.0	No	Ramp	Slope (%)	8.8	
No	Ramp Width (in)	39.0	Yes	Ramp	XSlope (%)	1.5	
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A	
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	1.5	N/A	Gutte	r X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A	
	X Walk 1 Direction	To NW		X Wa	lk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	5.4		X Wa	lk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	2.4		X Wa	lk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A	
	Obstruction Type			Storn	n Grate/Utility Type		
		N/A				N/A	
			Yes	Surfa	ce Condition? (G/P)	Good	