

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

4.6

2.2

N/A

No

N/A

3.5

2.4

N/A

N/A

N/A

N/A

N/A

Good

17.4

To SW

Intersection ID: 51441 Main Street: TAMARRON\_DR Cross Street: WOODLAND\_WATCH\_CT Location: E

ADA ID: 5BCA9B64C9E6 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

WOODLAND WATCH CT StopSign TAMARRON DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Yes N/A Ramp Length (in) 47.0 BlendTrans Slope (%) 48.0 No Yes Ramp Width (in) BlendTrans XSlope (%) N/A N/A Flare Type LT N/A Flare Type RT N/A Flare Slope LT (%) N/A N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To NW X Walk 2 Direction N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 2.5 X Walk 2 Slope (%) X Walk 1 X Slope (%) 1.3 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1?

0.6

3.9

N/A

N/A

N/A

N/A

Yes

No

Clear Space?

Curb Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)







N/A

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type