

Access Compliance Report Public Rights-of-Way (Curb Ramps)




Intersection ID: 23398 Main Street: SHARON_RD_WEST Cross Street: BRANDON_FOREST_DR Location: SE

ADA ID: 5C222A5CD834 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

SHARON RD WEST Signal BRANDON FOREST DR Signal Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2

Total Cost: \$ 3200.00

Field Measurements/Component Compilance						
	Compliance Description		Data	Compliance Description		Data
	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	8.5
	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.5
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
		X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
	N/A	X Walk 1 Width (in)	111.0	N/A	X Walk 2 Width (in)	113.0
		X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	3.8
		X Walk 1 X Slope (%)	2.9		X Walk 2 X Slope (%)	1.5
	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
		Road Slope (%)	3.1	N/A	Clear Space?	N/A
		Road X Slope (%)	6.7	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good





