cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•		-					
Intersection ID: N/A	Main Str	Main Street: BRECKFIELD_CT			HALKIRK_MANOR_L	Location:	NE		
ADA ID: 5CAE0B9D6602	Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
	CALLON M	Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.7
	A CONTRACTOR	Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.2
	A	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
2° 1 198-17	A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	102			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A Distance			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	TATAL -	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	TEL CONTRACTOR	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
The IA CAL	A A A			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
<u>a</u>	1112			N/A	Shared Landing?	N/A			
	1111 10	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	n. 1 1 4. 17	R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A BACK MY		1004.2.2, 1004.0.0		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	1 111 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BRECKFIELD CT	-			X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	2.0
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.5		X Walk 2 X Slope (%)	4.5
Street 2 Name	HALKIRK MANOR LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	4.0	N/A	Clear Space?	N/A
	etepe.g				Road X Slope (%)	1.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00	197	Obstruction Type	174		Storm Grate/Utility Type	10/5
		ισταί σσοτ. φ	5250.00		Obstruction Type	N/A		otomi Grate/Otimity Type	N/A
						IN/A			N/A

Yes Surface Condition? (G/P)

Good

