## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



|   |                           | •                     |         |         | -  |                       |           |                          |                             | I     |  |
|---|---------------------------|-----------------------|---------|---------|--|-----------------------|-----------|--------------------------|-----------------------------|-------|--|
| Intersection ID: 17870                  | Main Street: HILLSDALE_AV |                       |         | Cross   | Street:  | TRANQUIL_AV           | Location: | SE                       |                             |       |  |
| ADA ID: 5D0707EE4911                    | Ramp Ty                   | Ramp Type: Perp       |         |         | Initial Pass/Fail: Fail Overall Compliance: No |                       |           |                          | o Severity Score:           | 61.25 |  |
| Codes/Mitigation Info/Possible Solution |                           |                       |         |         | Field Measurements/Component Compliance        |                       |           |                          |                             |       |  |
|   |                           | Possible Solutions:   |         |         | Compliance Description Date                    |                       |           | a Compliance Description |                             | Data  |  |
|   | 1                         | Remove & Replace Enti | ire Ram | n       | N/A  | Ramp Length (in)      | 55.0      | No                       | Ramp Slope (%)              | 8.8   |  |
|   | A ast                     |                       |         | Ρ.      | No   | Ramp Width (in)       | 38.0      | No                       | Ramp XSlope (%)             | 10.2  |  |
|   | 19 April                  |                       |         |         | N/A  | Flare Type LT         | N/A       | N/A                      | Flare Type RT               | N/A   |  |
| and the second                          | JAN.                      |                       |         |         | N/A  | Flare Slope LT (%)    | N/A       | N/A                      | Flare Slope RT (%)          | N/A   |  |
| - Article                               | 11                        |                       |         |         | N/A  | Flare Traversable LT? | N/A       | N/A                      | Flare Traversable RT?       | N/A   |  |
|   | CHA V                     |                       |         |         | N/A  | Landing Length (in)   | N/A       |                          | DWS Provided?               | N/A   |  |
| URANQUIL AN                             |                           | Surveyor Notes:       |         |         | N/A  | Landing Width (in)    | N/A       | N/A                      | DWS Contrast?               | N/A   |  |
| the second                              | L.                        | N/A                   |         |         | N/A  | Landing Slope (%)     | N/A       | N/A                      | DWS Length (in)             | N/A   |  |
|   | <u></u>                   | N/A                   |         |         | N/A  | Landing X Slope (%)   | N/A       | N/A                      | DWS Full Width?             | N/A   |  |
| A                                       |                           |                       |         | N/A     | Landing Curb? (Y/N)                            | N/A                   | N/A       | DWS Offset (in)          | N/A                         |       |  |
|   | 1 1 1 1                   | 6                     |         |         | N/A  | Shared Landing?       | N/A       |                          | DWS Oliset (III)            | N/A   |  |
| THE STATE                               | The second second         | PROW/ADA:             |         |         | N/A  | 9                     | N/A       | N/A                      | Cuttor Slope (0)            | N/A   |  |
|   | - · ·                     |                       |         |         | Gutter Ponding?                                |                       |           | Gutter Slope (%)         |                             |       |  |
|   | Not Found, R304.5.1, R    | 304.2.2               | ,       | N/A     | Gutter Lip Ht (in)                             | N/A                   |           | Gutter X Slope (%)       | N/A                         |       |  |
| Jan                                     | R304.5.3, R302.7          |                       |         | N/A     | Painted X Walk1?                               | No                    | N/A       | Painted X Walk2?         | N/A                         |       |  |
| about a state                           |                           |                       |         |         | X Walk 1 Direction                             | To NE                 |           | X Walk 2 Direction       | N/A                         |       |  |
|   |                           |                       |         | N/A     | X Walk 1 Width (in)                            | N/A                   | N/A       | X Walk 2 Width (in)      | N/A                         |       |  |
|   | TRANQUIL AV               |                       |         |         |  | X Walk 1 Slope (%)    | 2.1       |                          | X Walk 2 Slope (%)          | N/A   |  |
| Stop Condition-Street 2                 | None                      |                       |         |         |  | X Walk 1 X Slope (%)  | 7.0       |                          | X Walk 2 X Slope (%)        | N/A   |  |
| Street 2 Name                           | N/A                       |                       |         |         | N/A  | Ramp inside XWalk1?   | N/A       | N/A                      | Ramp inside XWalk2?         | N/A   |  |
| Stop Condition-Street 1                 | N/A                       |                       |         |         |  | Road Slope (%)        | N/A       | N/A                      | Clear Space?                | N/A   |  |
|   |                           |                       |         |         |  | Road X Slope (%)      | N/A       | N/A                      | Clear Space to XWalk (in)   | N/A   |  |
|   |                           |                       |         |         | N/A  | Any Obstructions?     | N/A       | N/A                      | Storm Grate/Utility Hazard? | N/A   |  |
|   |                           | Total Cost:           | \$      | 1850.00 |  | Obstruction Type      |           |                          | Storm Grate/Utility Type    |       |  |
|   |                           |                       |         |         |  |                       | N/A       |                          |                             | N/A   |  |

**No** Surface Condition? (G/P)

Poor

