

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

9.5

0.3

N/A

Yes

To N

105.0

4.8

3.1

Yes

N/A

N/A

N/A

N/A

Good

Intersection ID: 19146 Main Street: TYVOLA RD Cross Street: WEDGEWOOD DR Location: SW **Overall Compliance: No Severity Score:** ADA ID: 5D1F83483CA2 Ramp Type: PerpDiag Initial Pass/Fail: Fail 12.5

**Codes/Mitigation Info/Possible Solution** 

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

22.0

78.0

N/A

Yes

To E

104.0

3.3

3.3

Yes

1.4

4.4 N/A

N/A



WEDGEWOOD DR Street 1 Name Signal Stop Condition-Street 2 **TYVOLA RD** Street 2 Name Stop Condition-Street 1 Signal Possible Solutions: Compliance Description N/A Remove & Replace Curb Ramp With Two New Directional Ramps or Yes Equivalent. N/A N/A N/A N/A Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.2.2 N/A N/A N/A

Total Cost: 3200.00

X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A Any Obstructions? **Obstruction Type** 

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

Flare Traversable LT?

Flare Type LT





