

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.3

0.7

N/A

Cross Street: SEDGEWOOD FOREST LN Intersection ID: 31816 Main Street: SEDGEWOOD CR Location: NE **Severity Score:** ADA ID: 5D7C466E958B Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Data

47.0

42.0

N/A



SEDGEWOOD FOREST LN Street 1 Name Stop Condition-Street 2 StopSign **SEDGEWOOD CR** Street 2 Name Stop Condition-Street 1 None Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: R304.5.1

N/A Ramp Length (in) No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A

Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? **Gutter Ponding?** Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) Road X Slope (%) Any Obstructions? **Obstruction Type**

Compliance Description

N/A N/A Flare Slope RT (%) N/A N/A N/A Flare Traversable RT? N/A N/A N/A DWS Provided? N/A N/A N/A **DWS Contrast?** N/A N/A N/A DWS Length (in) N/A N/A N/A DWS Full Width? N/A N/A N/A DWS Offset (in) N/A N/A N/A N/A Gutter Slope (%) N/A N/A N/A Gutter X Slope (%) N/A No N/A Painted X Walk2? No To SW X Walk 2 Direction To SE N/A X Walk 2 Width (in) N/A X Walk 2 Slope (%) 2.7 3.1 6.1 X Walk 2 X Slope (%) 4.9 N/A N/A Ramp inside XWalk2? N/A 0.6 N/A Clear Space? N/A N/A 6.9 Clear Space to XWalk (in) N/A N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)





Total Cost:



3200.00