

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.1

2.5

N/A

No

N/A

1.6

6.2

N/A

N/A

N/A

N/A

N/A

Good

To NE

Intersection ID: 14147 Main Street: CHERRY ST **Cross Street: LUTHER ST** Location: W

Overall Compliance: No ADA ID: 5DF304AC1D53 Ramp Type: Perpendicular Diagonal Initial Pass/Fail: Fail Severity Score: 18.75

Compliance Description

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Data



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **CHERRY ST** StopSign **LUTHER ST** Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.5.3

StopSign

Yes N/A Ramp Length (in) 46.0 Ramp Slope (%) No Ramp XSlope (%) No Ramp Width (in) 32.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To SE X Walk 2 Direction N/A N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 0.6 X Walk 2 Slope (%) X Walk 1 X Slope (%) 3.2 X Walk 2 X Slope (%) N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Road Slope (%) 1.5 N/A Clear Space? N/A Road X Slope (%) Clear Space to XWalk (in) 4.4 N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? **Obstruction Type** Storm Grate/Utility Type

N/A

Yes

Surface Condition? (G/P)





Total Cost:



3200.00