cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 49150 | 150 Main Street: VIDAL_LN | | Cross Street: DACAVIN_DR | | | | Location: | NE |
|---|-----------------------------|----------|--|-----------------------|-------|-----------------------------|-----------------------------|-------|
| ADA ID: 5F9CE9753B29 | BB29 Ramp Type: BlendTrans1 | | Initial Pass/Fail: Fail Overall Compliance: No | | | | Severity Score: | 33.75 |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | |
| | Possible Solutions: | | | | | Compliance Description Data | | |
| | Remove & Replace Curb Ra | amp With | N/A | Ramp Length (in) | 48.0 | Yes | BlendTrans Slope (%) | 3.0 |
| | Two New Directional Ramp | • | No | Ramp Width (in) | 47.0 | No | BlendTrans XSlope (%) | 11.7 |
| | Equivalent. | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| VIDAL LIN & S | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| & Y O | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | N/A | Shared Landing? | N/A | | | |
| | PROW/ADA: | | N/A | Gutter Ponding? | N/A | | Gutter Slope (%) | N/A |
| | Not Found, R304.5.1, R304 | 53 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| | | 1010 | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| | | | | X Walk 1 Width (in) | N/A | | X Walk 2 Width (in) | N/A |
| Street 1 Name DAC | CADIN DR | | | X Walk 1 Slope (%) | 5.2 | | X Walk 2 Slope (%) | N/A |
| Stop Condition-Street 1 | None | | | X Walk 1 X Slope (%) | 13.6 | | X Walk 2 X Slope (%) | N/A |
| Street 2 Name | N/A | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 2 | N/A | | | Road Slope (%) | 13.6 | | Clear Space? | N/A |
| | | | | Road X Slope (%) | 5.2 | N/A | Clear Space to XWalk (in) | N/A |
| | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | N/A | | | N/A |







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.3