cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 29810 | : 29810 Main Street: MCCLURE_MANOR_DR | | | | SYDENHAM_CT | Location: | sw | | | |
|---|---------------------------------------|------------------------------|-----------|--|-----------------------|-----------|-----------------------------|-----------------------------|------|--|
| | | | | | | | | | | |
| ADA ID: 6067F8D7BAD6 Ramp Type: Perp | | | Initial P | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 25 | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | |
| | Contrast. | Possible Solutions: | | Compliance Description | | | Data Compliance Description | | Data | |
| | | Remove & Replace Entire Ramp |). | N/A | Ramp Length (in) | 47.0 | Yes | Ramp Slope (%) | 8.0 | |
| | 101 | | | Yes | Ramp Width (in) | 53.0 | No | Ramp XSlope (%) | 8.2 | |
| | h 12/-1 | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| and all the same | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| 6 | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| MOOLURE MANOR DR | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| in the | A CONTRACTOR | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| A CONTRACTOR | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| | | | | N/A | Shared Landing? | N/A | | | | |
| | ONP | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | SIAN | Not Found, R304.5.3 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | |
| | | | | | X Walk 1 Direction | To N | | X Walk 2 Direction | N/A | |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name MCCL | URE MANOR DR | | | | X Walk 1 Slope (%) | 0.2 | | X Walk 2 Slope (%) | N/A | |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 7.0 | | X Walk 2 X Slope (%) | N/A | |
| Street 2 Name | N/A | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | N/A | | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | Total Cost: \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | | N/A | | | N/A | |

