

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.0

7.1

N/A

N/A

N/A

Intersection ID: 27163Main Street:HEATHERTON_PLCross Street:PROVIDENCE_ARBOURS_DRLocation:NWADA ID: 60CF28D92BC8Ramp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Compliance Description

N/A

Yes

N/A

N/A

N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Traversable LT?

Flare Type LT

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Data

46.5

74.0

N/A

N/A

N/A



Street 1 Name HEATHERTON PL
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:
Remove & Replace Entire Ramp.
•
Surveyor Notes:
N/A
PROW/ADA:
Not Found, R304.5.3



Total Cost:



1850.00



N/A Landing Length (in) N/A N/A **DWS Provided?** N/A N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? N/A X Walk 1 Direction To S X Walk 2 Direction N/A N/A N/A X Walk 2 Width (in) X Walk 1 Width (in) N/A X Walk 1 Slope (%) 6.2 X Walk 2 Slope (%) N/A X Walk 1 X Slope (%) 0.2 X Walk 2 X Slope (%) N/A N/A N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? N/A Road Slope (%) N/A N/A Clear Space? N/A N/A Road X Slope (%) N/A Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good