cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

N/A

Intersection ID: 29139	: 29139 Main Street: BALSAM_TREE_DR		ross Street: STONEY_VALLEY_CT				NE
ADA ID: 61330538EFB3	e 1330538EFB3 Ramp Type: BlendTrans1			tial Pass/Fail: Pass Overall Compliance: No			10
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance				
	Possible Solutions:	Con	Compliance Description Data		Compliance Description		Data
	Remove & Replace Curb Ramp	With N/A	Ramp Length (in)	42.0	Yes	BlendTrans Slope (%)	1.6
	Two New Directional Ramps or	Yes	Ramp Width (in)	140.0	Yes	BlendTrans XSlope (%)	1.6
	Equivalent. Utility Present.	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
	ALL ALL	N/A	Flare Slope LT (%)	2.8	N/A	Flare Slope RT (%)	5.0
		N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
		Yes	Landing Length (in)	55.0	No	DWS Provided?	No
	Surveyor Notes:	Yes	Landing Width (in)	112.0	N/A	DWS Contrast?	No
Bos b	N/A	No	Landing Slope (%)	2.8	N/A	DWS Length (in)	N/A
CALLAND THE SAL		Yes	Landing X Slope (%)	0.8	N/A	DWS Full Width?	No
the training of the second sec	The second se	N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
The provide a second second		N/A	Shared Landing?	No			
	PROW/ADA:	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.8
Ramon II I Hand Care I	R304.2.2-Perp, R304.3.2-Para, R	305. Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.6
	R302.3, R402.2	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
			X Walk 1 Direction	To W		X Walk 2 Direction	To S
The state of the	hi has		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name STONEY VA	ALLEY CT		X Walk 1 Slope (%)	5.4		X Walk 2 Slope (%)	2.7
Stop Condition-Street 1	StopSign		X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	4.0
Street 2 Name BALSAM	TREE DR	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None		Road Slope (%)	0.9		Clear Space?	Yes
			Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
		Yes	Any Obstructions?	No	No	Storm Grate/Utility Hazard?	No
	Total Cost: \$	3200.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A



