

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

8.8

3.8

N/A N/A

N/A N/A

N/A

N/A N/A N/A

N/A

N/A

No To SE N/A

1.5

4.0

N/A

N/A

N/A

N/A

N/A Good

Main Street: CARLEEN WAY DR **Cross Street: GRIER SPRINGS LN** Location: Intersection ID: 31500 NW Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** 22.5 ADA ID: 63008A504BCA **Severity Score:** 

Compliance Description

Ramp Length (in)

N/A

**Codes/Mitigation Info/Possible Solution** 

N/A

Field Measurements/Component Compliance

58.5 No

**Data Compliance Description** 

Ramp Slope (%)



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

**CARLEEN WAY DR** None **GRIER SPRINGS LN** StopSign Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes:

Not Found, R304.5.1, R304.2.2, R304.5.3

PROW/ADA: Total Cost: 3200.00

No	Ramp Width (in)	38.0	No	Ramp XSlope (%)
N/A	Flare Type LT	N/A	N/A	Flare Type RT
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?
N/A	Landing Length (in)	N/A	N/A	DWS Provided?
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)
N/A	Shared Landing?	N/A		
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?
	X Walk 1 Direction	To SW		X Walk 2 Direction
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)
	X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)
	X Walk 1 X Slope (%)	1.6		X Walk 2 X Slope (%)
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?
	Road Slope (%)	4.0	N/A	Clear Space?
	Road X Slope (%)	0.6	N/A	Clear Space to XWalk (in)
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?
	Obstruction Type			Storm Grate/Utility Type
		N/A		
			Yes	Surface Condition? (G/P)





