

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 16837	Main Street: CEDARWILD_RD	Cross Street: ELM_FOREST_DR	Location: E
ADA ID: 634043B76B8A	Ramp Type: ParaDiag	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 17.5	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

ASP LIP 1.0, LT RP < 5%

PROW/ADA:

Not Found, R304.2.1, R304.5.3, R305, R302.7.2

Street 1 Name	ELM FOREST DR
Stop Condition-Street 1	None
Street 2 Name	CEDARWILD RD
Stop Condition-Street 2	StopSign

Total Cost: \$ 3950.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	49.0	N/A	Ramp Length RT (in)	60.0
Yes	Ramp Width LT (in)	56.0	Yes	Ramp Width RT (in)	48.0
Yes	Ramp Slope LT (%)	4.5	Yes	Ramp Slope RT (%)	7.4
Yes	Ramp XSlope LT (%)	1.6	Yes	Ramp XSlope RT (%)	0.2
Yes	Landing Length (in)	49.5	No	DWS Provided?	No
No	Landing Width (in)	40.0	N/A	DWS Contrast?	No
Yes	Landing Slope (%)	0.8	N/A	DWS Length (in)	N/A
No	Landing X Slope (%)	7.3	N/A	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.7
No	Gutter Lip Ht (in)	0.5	No	Gutter X Slope (%)	4.2
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	1.8
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	3.7
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	5.0	N/A	Clear Space?	Yes
	Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			Replace	Curb Slope (%)	8.7

