## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27272 Main Street: ELMSTONE_DR				Cross Street: STONEPATH_LN				SW
						Location:		
ADA ID: 668F9ABBD892 Ramp Type: PerpDiag		In	nitial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	13.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Possible Solutions:		Compliance Description		Data Compliance Description		Data
ST WORKER STORE THE REAL	Remove & Replace Cu	urb Ramp With	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	9.2
	and the second se	Two New Directional Ramps or Equivalent.	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.0
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
1998 8 G. G. C. C.				Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
ELMSTONE_DR	Contraction of the second seco	<i>₩</i>	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A we want		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
E E	Not Found, R304.2.2, I	R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
24			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	and the second sec			X Walk 1 Direction	To E		X Walk 2 Direction	To N
A CAN			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name STON	IEPATH LN			X Walk 1 Slope (%)	4.4		X Walk 2 Slope (%)	2.3
Stop Condition-Street 2	StopSign			X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	6.2
Street 2 Name ELM	STONE DR		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign			Road Slope (%)	1.2	N/A	Clear Space?	N/A
				Road X Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost:	\$ 3200.	00	Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

**Yes** Surface Condition? (G/P)

Good

