

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10587	ID: 10587 Main Street: CHARLES_AV				Cross Street: N_MCDOWELL_ST				
ADA ID: 67B31E5106CE Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description Date			Data	ta Compliance Description		Data
the state and	XXY	Remove & Replace Entire Ramp.	N/A	Ramp L	ength (in)	45.0	No	Ramp Slope (%)	10.2
	A		Yes	Ramp V	Vidth (in)	64.0	Yes	Ramp XSlope (%)	2.8
1 P La Ha	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		N/A	Flare T	ype LT	N/A	N/A	Flare Type RT	N/A
Contraction of the second	State /		N/A	Flare S	lope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	E CONTRACTOR		N/A	Flare Tr	aversable LT?	N/A	N/A	Flare Traversable RT?	N/A
and the second of the	A / /		N/A	Landing	J Length (in)	N/A	N/A	DWS Provided?	N/A
	1 2/2	Surveyor Notes:	N/A	Landing	y Width (in)	N/A	N/A	DWS Contrast?	N/A
CHARLES AV	C. C. Mail	N/A	N/A	Landing	J Slope (%)	N/A	N/A	DWS Length (in)	N/A
And State of Long States of Long States			N/A	Landing	J X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing	J Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second second	14 14 Da 17/1		N/A	Shared	Landing?	N/A			
	1 07 3	PROW/ADA:	N/A	Gutter I	Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A THE	Not Found, R304.2.2	N/A	Gutter I	₋ip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second second	and the second	,	N/A	Painted	X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk	1 Direction	To S		X Walk 2 Direction	N/A
	Store Law 1		N/A	X Walk	1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CHARLES AV			X Walk	1 Slope (%)	3.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None			X Walk	1 X Slope (%)	4.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp ir	nside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road S	lope (%)	N/A	N/A	Clear Space?	N/A
				Road X	Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/#	Any Ob	structions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 1	850.00	Obstruc	tion Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

