cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 20072	Main Street: AXIS_CT		Cross Street: FALLOW_LN				Location:	NW
ADA ID: 687AC88E1837	Ramp Type: BlendTrans1	In	nitial Pass/Fail: Pass Overall Compliance: No			Severity Score:	2.75	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description Data		Data	Compliance Description		Data
	Remove & Replac	ace Curb Ramp With	N/A	Ramp Length (in)	64.0	Yes	BlendTrans Slope (%)	3.1
	Two New Direction	-	Yes	Ramp Width (in)	74.0	No	BlendTrans XSlope (%)	2.1
	Equivalent.	·	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
	a ja		N/A	Flare Slope LT (%)	0.0	N/A	Flare Slope RT (%)	3.5
	10			Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
the la				Landing Length (in)	36.0	Yes	DWS Provided?	Yes
	Surveyor Notes:		Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
	N/A		Yes	Landing Slope (%)	1.1	Yes	DWS Length (in)	24.0
			Yes	Landing X Slope (%)	1.1	No	DWS Full Width?	No
11 An all and			N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.5
	A STATE OF			Shared Landing?	No			
	PROW/ADA:	PROW/ADA: Not Found, R304.5.3, R304.2.1, R305.1.4, R305.2		Gutter Ponding?	No	Yes	Gutter Slope (%)	0.4
				Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.1
the the				Painted X Walk1?	No	N/A	Painted X Walk2?	No
	A Mark			X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
	No. of Contraction of			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	AXIS CT			X Walk 1 Slope (%)	3.7		X Walk 2 Slope (%)	3.8
Stop Condition-Street 1	StopSign			X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	3.2
Street 2 Name FA	ALLOW LN		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None			Road Slope (%)	0.8		Clear Space?	Yes
				Road X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost:	\$ 3200.	0	Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

12.0