cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11553 Main Street: MCKINLEY_DR Cross Street: THORNTON_RD						Location:	N
ADA ID: 68B0E572E517 Ramp Ty	ype: BlendTrans1	Initial Pass/	Fail: Pass Overal	I Compliar	nce: N	o Severity Score	: 0
Codes/Mitigation Info		Field Measurements/Component Compliance					
Carlos Ca	Possible Solutions:	Con	Compliance Description Dat		a Compliance Description		Data
	Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	Nith N/A	Ramp Length (in)	47.0	Yes	BlendTrans Slope (%)	4.5
		Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	0.4
		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
		N/A	Flare Slope LT (%)	5.5	N/A	Flare Slope RT (%)	2.9
		N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
		Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
	Surveyor Notes:	Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes
	N/A	No	Landing Slope (%)	3.1	Yes	DWS Length (in)	24.0
		Yes	Landing X Slope (%)	1.1	Yes	DWS Full Width?	Yes
		N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
		N/A	Shared Landing?	No			
	PROW/ADA:	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	3.2
	Not Found, R304.2.2-Perp, R304.3	.3.2- Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.3
	Para	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name MCKINLEY DR			X Walk 1 Slope (%)	2.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1 StopSign			X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2 N/A			Road Slope (%)	0.2		Clear Space?	Yes
			Road X Slope (%)	2.7	N/A	Clear Space to XWalk (in)	N/A
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost: \$ 3	200.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

19.0