cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



								I	
Intersection ID: N/A	Main Str	reet: KIMMERLY_GLEN_LN	Cross Street: ENDOLWOOD DR			Location:	NE		
ADA ID: 68DE68837990	Ramp Ty	ype: Directional1	Initial Pass/Fail: Fail Overall Compliance: No			Severity Score:	37.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	PAUL AND AND	Possible Solutions:	Compliance Description		on Data	Data Compliance Description		Data	
	STIT	Remove & Replace Entire Ramp.	N/A	Ramp Length (ir	n) 38.0	N/A	Grade Break?	N/A	
		·······	Yes	Ramp Width (in)) 48.0	N/A	Grade Break Slope (%)	0.0	
Aller a			No	Ramp Slope (%)) 10.0	N/A	Grade Break XSlope (%)	0.0	
			No	Ramp XSlope (%	%) 8.7				
	BILL		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT ((%) N/A	N/A	Flare Slope RT (%)	0.0	
	Floren Alta	Surveyor Notes:	N/A	Flare Traversabl	le LT? N/A	N/A	Flare Traversable RT?	N/A	
G. K	Contraction of the second second	DWS LCOATED ON LNDG	N/A	Landing Length	(in) 0.0	N/A	DWS Provided?	N/A	
KIMMERLY_GL	ENLIN		N/A	Landing Width (i	in) 0.0	N/A	DWS Contrast?	N/A	
the second se			N/A	Landing Slope (%) 0.0	N/A	DWS Length (in)	N/A	
	A BOARD		N/A	Landing X Slope	e (%) 0.0	N/A	DWS Full Width?	N/A	
	S 41	PROW/ADA:	N/A	Landing Curb? ((Y/N) N/A	N/A	DWS Offset LT (in)	N/A	
A second the second to the		R304.2.2, R304.5.3	N/A	Shared Landing	? N/A	N/A	DWS Offset RT (in)	N/A	
1 and the second	Caller Karlow	,	N/A	Gutter Ponding?	? 0.0	N/A	Gutter Slope (%)	N/A	
To at The works	ALL MALL		N/A	Gutter Lip Ht (in) 0.0	N/A	Gutter X Slope (%)	N/A	
	The second second		N/A	Painted X Walk1	1? No		Road Slope (%)	3.1	
Street 1 Name	KIMMERLY GLEN LN			X Walk 1 Direction	on To SW		Road X Slope (%)	0.5	
Stop Condition-Street 1	StopSign			X Walk 1 Width	(in) N/A		Clear Space?	N/A	
Street 2 Name	N/A			X Walk 1 Slope	(%) 3.1	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A			X Walk 1 X Slop	oe (%) 0.5	N/A	Storm Grate/Utility Hazard?	N/A	
			N/A	Ramp inside XW	Valk1? N/A		Storm Grate/Utility Type		
			N/A	Any Obstruction	s? N/A			N/A	
		Total Cost: \$ 1	600.00	Obstruction Type	e	Yes	Surface Condition? (G/P)	Good	
					N/A	N/A	Curb Slope (%)	0.8	

