


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|---------------------------|--------------------------|-------------------------|------------------------|
| Intersection ID: 10031454 | Main Street: MCDONALD_AV | Cross Street: N/A | Location: SW |
| ADA ID: 69BBF57B0739 | Ramp Type: Perp | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | | Severity Score: 58.75 |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | |
|----------------------------------------------------------------------------------|-----------------------------------------|------------|-----------------------------------------|-----------------------|-------|-----------------------------|--------------------------|------|
|  | Possible Solutions: | | Compliance | Description | Data | Compliance | Description | Data |
| | Remove & Replace Entire Ramp. | | N/A | Ramp Length (in) | 47.0 | No | Ramp Slope (%) | 17.0 |
| | | | No | Ramp Width (in) | 46.0 | No | Ramp XSlope (%) | 10.8 |
| | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| Surveyor Notes: | N/A | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | | | N/A | Shared Landing? | N/A | | | |
| | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | Not Found, R304.5.1, R304.2.2, R304.5.3 | | N/A | Gutter Lip Ht (in) | 1.0 | N/A | Gutter X Slope (%) | N/A |
| | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | N/A |
| | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | | | | X Walk 1 Slope (%) | 1.2 | | X Walk 2 Slope (%) | N/A |
| | | | | X Walk 1 X Slope (%) | 12.4 | | X Walk 2 X Slope (%) | N/A |
| | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | N/A | | N/A | |
| | | | | | | Yes | Surface Condition? (G/P) | Good |
| Total Cost: | | \$ 1850.00 | | | | | | |

