

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 51371 Main Street: UNIVERSITY\_POINTE\_BV Cross Street: N\_TRYON\_ST Location: NE **Overall Compliance: No** ADA ID: 69C2BB299052 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 10

Codes/Mitigation Info/Possible Solution



The second secon	
Street 1 Name	UNIVERSITY POINTE BV
Stop Condition-Street 2	Signal
Street 2 Name	N/A
Stop Condition-Street 1	N/A

/Possible Solution		Field Measurements/Component Compliance					
Possible Solutions:		Comp	liance Description	Data	Complian	ce Description	Data
Remove & Replace Entire R	Ramp.	N/A	Ramp Length (in)	96.0	Yes R	amp Slope (%)	5.2
•	-	No	Ramp Width (in)	47.0	Yes F	amp XSlope (%)	2.1
		N/A	Flare Type LT	N/A	N/A F	lare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A F	lare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	<b>N/A</b> F	lare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	WS Provided?	N/A
Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	WS Contrast?	N/A
N/A		N/A	Landing Slope (%)	N/A	N/A	WS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	WS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	WS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	outter Slope (%)	N/A
Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	outter X Slope (%)	N/A
		N/A	Painted X Walk1?	No	N/A F	ainted X Walk2?	N/A
			X Walk 1 Direction	To S	×	Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A X	Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	2.1	×	Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	3.8	×	Walk 2 X Slope (%)	N/A
		N/A	Ramp inside XWalk1?	N/A	N/A F	amp inside XWalk2?	N/A
			Road Slope (%)	N/A	N/A	lear Space?	N/A
			Road X Slope (%)	N/A	N/A	lear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A S	torm Grate/Utility Hazard?	N/A
Total Cost:	\$ 1850.00		Obstruction Type		S	torm Grate/Utility Type	
				N/A			N/A
					Yes S	urface Condition? (G/P)	Good





