

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| ntersection ID: 48245 Main Street: LANIER_ISLANDS_CR | | | ross Street: LAKE_ERIE_LN | | | | Location: | NE | |
|--|------------------------------|-----------|--|-----------------------|-------|-----------------------------|-----------------------------|-------|--|
| ADA ID: 69CA2B8BDFCA Ramp Type: PerpDiag | | Initial P | itial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 12.5 | |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | | |
| | Possible Solutions: | | Compliance Description | | | Data Compliance Description | | | |
| | Remove & Replace Curb Ramp W | Vith | N/A | Ramp Length (in) | 48.0 | Yes | Ramp Slope (%) | 5.6 | |
| | Two New Directional Ramps or | | Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 6.7 | |
| | Equivalent. | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| 6 b | - | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| that any marked that the | 2 | | N/A | Shared Landing? | N/A | | | | |
| | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | Not Found, R304.5.3 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| | | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | To SW | |
| | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name LANIER ISLANDS CR | _ | | | X Walk 1 Slope (%) | 1.3 | | X Walk 2 Slope (%) | 4.2 | |
| Stop Condition-Street 2 StopSign | | | | X Walk 1 X Slope (%) | 4.7 | | X Walk 2 X Slope (%) | 2.5 | |
| Street 2 Name LAKE ERIE LN | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 None | | | | Road Slope (%) | 5.7 | N/A | Clear Space? | N/A | |
| | | | | Road X Slope (%) | 4.6 | N/A | Clear Space to XWalk (in) | N/A | |
| | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Total Cost: \$ 32 | 200.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | N/A | | / | N/A | |

Yes Surface Condition? (G/P) Good



