

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14283 Main Street: AROSA_AV				root		Location:	SE			
			Cross Street: DILWORTH_RD							
ADA ID: 69D7FA6B01E3 Ramp Type: Directional1		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description			Data	Data Compliance Description			
		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	51.0	N/A	Grade Break?	N/A	
				Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
The state of the s				Yes	Ramp Slope (%)	5.2	N/A	Grade Break XSlope (%)	0.0	
Strander Mail of the	一次急 和 四			No	Ramp XSlope (%)	2.5				
An is a start of the start of t	A MAG			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	ALAV	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
E B L		N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	C. Martin			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	V.4.X	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
The Filt				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	S. dana tile			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
The second secon				N/A	Painted X Walk1?	No		Road Slope (%)	7.3	
Street 1 Name	AROSA AV				X Walk 1 Direction	To N		Road X Slope (%)	1.8	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	7.3	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.8	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	5.8	

